

29th International Conference on Structural Failures (ICSF 2019)

MATEC Web of Conferences Volume 284 (2019)

Miedzyzdroje, Poland
20 - 24 May 2019

Editor:

Maria Kaszynska

ISBN: 978-1-5108-9069-5

Printed from e-media with permission by:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571



Some format issues inherent in the e-media version may also appear in this print version.

This work is licensed under a Creative Commons Attribution 4.0 International License. License details:
<http://creativecommons.org/licenses/by/4.0/>.

No changes have been made to the content of these proceedings. There may be changes to pagination and minor adjustments for aesthetics.

Printed by Curran Associates, Inc. (2019)

For additional information, please contact EDP Sciences – Web of Conferences at the address below.

EDP Sciences – Web of Conferences
17, Avenue du Hoggar
Parc d'Activité de Courtabœuf
BP 112
F-91944 Les Ulis Cedex A
France

Phone: +33 (0) 1 69 18 75 75

Fax: +33 (0) 1 69 28 84 91

contact-edps@webofconferences.org

Additional copies of this publication are available from:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571 USA
Phone: 845-758-0400
Fax: 845-758-2633
Email: curran@proceedings.com
Web: www.proceedings.com

TABLE OF CONTENTS

PREFACE	1
<i>Kaszynska Maria</i>	
ANALYSIS OF TECHNICAL CONDITION OF FOOTBRIDGES OVER THE RAILWAYS IN DANGER OF COLLAPSE	2
<i>Chmielewski Ryszard, Bak Aleksandra</i>	
DAMAGE TO AN OVERPASS BRIDGE FROM WBS PREFAB BEAMS	12
<i>Furtak Kazimierz, Hebda Mariusz</i>	
REVITALIZATION OF HISTORIC RAILWAY BRIDGES ON THE EXAMPLE OF A STRUCTURE IN LEKNICA (POLAND)	21
<i>Juszczak Artur</i>	
IMPROVEMENT OF THE LOAD CAPACITY OF THE ROAD OVERPASS AS A RESULT OF REPAIRS AFTER BREAKAGE CAUSED BY VEHICLE IMPACTS	29
<i>Miskiewicz Mikołaj, Bruski Dawid, Chróscielewski Jacek, Wilde Krzysztof</i>	
ANALYSIS OF THE TECHNICAL CONDITION OF A RAILWAY BRIDGE AT RISK OF FAILURE	38
<i>Piechota Mieczysław, Rogojsz Grzegorz</i>	
THE IMPACT OF ROAD INFRASTRUCTURE FAILURES ON TRAFFIC CONDITIONS AND TRAVEL BEHAVIOUR IN URBAN AREAS – THE CASE OF THE LAZIENKOWSKI BRIDGE IN WARSAW	47
<i>Szarata Andrzej, Nosal Hoya Katarzyna</i>	
DURABILITY AND MODERN TECHNOLOGIES OF STRENGTHENING CULVERTS AND ANIMAL CROSSINGS	61
<i>Wysokowski Adam</i>	
ASSESSMENT OF TECHNICAL CONDITION AND REPAIR OF STEEL STRUCTURE ELEMENTS ON THE EXAMPLE OF FIRE DAMAGE IN A WAREHOUSE BUILDING	71
<i>Ambroziak Andrzej, Piotrkowski Paweł, Heiżig Tomasz</i>	
ANALYSIS OF REPAIR WORKS TO REMOVE THE EFFECTS OF STRUCTURAL FAILURE AFTER A GAS EXPLOSION	80
<i>Bak Aleksandra, Chmielewski Ryszard</i>	
IMPACT OF IMPROPER STORAGE AND INSTALLATION OF GLAZED FIRE RATED WALLS ON THEIR PERFORMANCE	91
<i>Kinowski Jacek, Sulik Paweł, Sedlak Bartłomiej</i>	
VENTILATED FAÇADE SYSTEMS. DESIGN AND WORKMANSHIP FAULTS AFFECTING THE FUNCTIONALITY AND SAFE USE	102
<i>Kopyłow Oleksij</i>	
DIAGNOSTICS OF THE STRUCTURAL FAILURE OF SPORTS HALL EXTERNAL WALL LAYERS	111
<i>Kruszka Leopold, Muzolf Paweł</i>	
DESIGN ERRORS OF THE EXTERNAL LIFT SHAFT AND THEIR NEGATIVE IMPACT ON THE OPERATION OF THE CLINIC BUILDING	124
<i>Niedostatkiwicz Maciej, Majewski Tomasz, Ziółkowski Patryk</i>	
EMERGENCY OVERFLOWS – CONSEQUENCES OF NON-COMPLIANCE WITH THE CONSTRUCTION LAW	135
<i>Polarczyk Iwona, Fijewski Michał</i>	
DEFECTS OF SANDWICH WALLS	143
<i>Stawiski Bohdan</i>	
THE ANALYSIS OF THE CAUSES OF THE COLLAPSE OF TWO TIMBER SHEDS DURING THE CONSTRUCTION	152
<i>Szczotka Józef</i>	
CHANGE IN GROUNDWATER CONDITIONS AS A CAUSE OF STRUCTURAL FAILURE – SELECTED CASE STUDIES	161
<i>Godlewski Tomasz, Bogusz Witold, Kaczynski Lukasz</i>	
ANALYSIS OF FAILURE IN LANDFILL CONSTRUCTION ELEMENTS	171
<i>Koda Eugeniusz, Grzyb Malgorzata, Osinski Piotr, Vaverková Magdalena D.</i>	
AN EXAMPLE OF FAILURE OF AN OFFICE BUILDING IN UPPER SILESIA	183
<i>Konieczny Kazimierz, Słowik Leszek</i>	

GEOTECHNICAL FAILURE OF A SLOPE FEATURING SITE DEVELOPMENT WITH INDUSTRIAL FACILITIES CAUSED BY IRRESPONSIBLE LEVELING IN THE NEIGHBORING AREA	195
<i>Kumor Maciej Kordian, Kumor Lukasz Aleksander</i>	
RECTIFICATION AND STABILIZATION OF THE FOUNDATION AS AN OPPORTUNITY IN REFERENCE TO PREVENTING CONSTRUCTION FAILURES AS REGARDS TRANSFORMER STATION FACILITIES LOCATED ON A WIND FARM	209
<i>Kuszyk Rafal, Gniwek Anna, Walczak Krzysztof</i>	
EXCAVATION SUPPORT – GEOTECHNICAL FAILURES IN THE CONTEXT OF DESIGN AND EXECUTION ERRORS AS WELL AS FORMAL AND ECONOMIC CONDITIONS.....	226
<i>Maca Natalia, Sierant Jakub</i>	
METHOD OF THERMAL DETECTION OF LEAKAGES IN CONSTRUCTION OF DEEP EXCAVATION: A REAL CASE STUDY IN POLAND.....	239
<i>Radzicki Krzysztof, Rybianski Lukasz, Popielski Pawel</i>	
CAUSES OF FAILURE OF A FOUR-STOREY BUILDING AND THE RECONSTRUCTION CONCEPT.....	248
<i>Rzezniczak Jerzy, Mlynarek Zbigniew, Gogolik Slawomir, Michalak Joanna</i>	
THE DELAYED EFFECTS OF FLOODING A RESIDENTIAL BUILDING – CASE STUDY.....	261
<i>Straz Grzegorz</i>	
DISCONTINUOUS TERRAIN DEFORMATION - FORECASTING AND CONSEQUENCES OF THEIR OCCURRENCE FOR BUILDING STRUCTURES	271
<i>Szojda Leszek, Wandzik Grzegorz</i>	
PILE BEARING ANALYSIS BASED UPON ULTIMATE VALUES OF TOE AND SKIN RESISTANCE AS WELL AS THEIR MOBILIZATION WITH SETTLEMENT	283
<i>Zarkiewicz Krzysztof</i>	
CAUSES OF DAMAGE AND METHODS OF REPAIRING FLOOR MADE ON POLYSTYRENE CONCRETE	294
<i>Drobiec Lukasz, Piotrkowski Pawel</i>	
CAUSES OF FAILURES OF INDUSTRIAL FLOORS AND CONCRETE SURFACES – CASE STUDY	306
<i>Kiernozycycki Wlodzimierz, Blyzko Jaroslaw</i>	
COMMERCIAL BUILDING FLOORING FAILURE CAUSED BY SWELLING OF THE FOUNDATION LAYERS.....	316
<i>Kwiecien Slawomir</i>	
FAILURE OF A WAREHOUSE FLOOR BY SUBSOIL SETTLEMENT.....	327
<i>Kwiecien Slawomir</i>	
FLOOR DEFECTS IN QUARTERS OVER RAILWAY TUNNEL CAUSED BY DESIGN AND CONSTRUCTION ERRORS	338
<i>Majewski Tomasz, Niedostatkiewicz Maciej, Ziolkowski Patryk</i>	
CAUSES AND CONSEQUENCES OF A CONSTRUCTION DISASTER IN A HISTORIC CHURCH	349
<i>Bednarz Lukasz, Opalka Piotr</i>	
CAUSE-AND-EFFECT STUDY OF THE STRUCTURAL FAILURE OF THE HISTORIC COMPLEX OF THE ST. ANNA’S CHURCH IN WARSAW.....	359
<i>Chmielewski Ryszard, Kruszka Leopold</i>	
THE METHOD OF STRENGTHENING THE CHURCH BUILDING IN TERMS OF THE PLANNED MINING EXPLOITATION.....	368
<i>Drobiec Lukasz, Niemiec Tomasz, Kawulok Marian, Slowik Leszek, Chomacki Leszek</i>	
CONTRACTOR ERRORS AS THE CAUSE OF EMERGENCY CONDITIONS OF A TIMBER ROOF RAFTER FRAMING	380
<i>Dybel Piotr, Jaskowska-Lemanska Justyna, Kucharska Milena</i>	
ANALYSIS OF REMOVAL METHOD OF A 19TH CHURCH’S DEFLECTION.....	390
<i>Gromysz Krzysztof</i>	
CRACKING OF THE VAULT IN A CHURCH BUILDING AND ACTIVITIES UNDERTAKEN IN THE VIEW OF THE FURTHER MINING EXPLOITATION	402
<i>Kawulok Marian, Chomacki Leszek, Rutkowski Tadeusz</i>	
SAFETY ASSESSMENT OF STRENGTHENED FLOOR SLAB STRUCTURES IN A HISTORIC DEPARTMENT STORE IN WROCLAW.....	412
<i>Kruszka Leopold</i>	
SELECTED PROBLEMS OF FAILURES AND REPAIRS OF HISTORIC MASONRY VAULTS.....	425
<i>Nowak Rafal, Orlowicz Romuald</i>	

THE DIAGNOSIS OF THE TECHNICAL CONDITION OF BUILDINGS AS AN INDICATOR OF THE SCALE OF NEEDS FOR THE REVITALIZATION ON THE EXAMPLE KOZUCHÓW	433
<i>Nowogonska Beata</i>	
ABOUT PROBLEMS WITH CAST IRON COLUMNS OF THE REVITALIZED POST-INDUSTRIAL BUILDINGS	443
<i>Urban Tadeusz, Goldyn Michal</i>	
THE ANALYSIS ON CAUSES OF FAILURE AND STRENGTHENING OF FOUNDATION SLAB WITH PRE-TENSIONED CFRP STRIPES	454
<i>Bartosik Tomasz, Szefer Mariusz, Majchrzyk Lukasz</i>	
COMMON THERMAL AND SHRINKAGE CRACKING OF CEILING SLABS.....	463
<i>Hulimka Jacek, Dawczynski Szymon, Krzywon Rafal</i>	
CONSIDERABLE CRACKING IN THE FOUNDATION SLAB IN A MULTI-STOREY UNDERGROUND GARAGE.....	472
<i>Maj Marek, Tamrazyan Ashot, Ubysz Andrzej</i>	
ANALYSIS OF THE CAUSES OF DAMAGE TO THE RC FLOOR SLAB IN THE UNDERGROUND GARAGE.....	483
<i>Matysek Piotr, Witkowski Michal</i>	
EFFECTIVENESS OF STRENGTHENING PRE-LOADED RC BEAMS WITH CFRP STRIPS IN CONVENTIONAL AND ACCELERATED STRENGTHENING PROCEDURES	491
<i>Michalowska-Maziejuk Dorota, Goszczynska Barbara, Trampczynski Wieslaw</i>	
LEAKPROOFNESS OF THE REINFORCED CONCRETE TANK FOR WATER WITH A CAPACITY OF 45000 M3.....	502
<i>Maciej Y. Minch, Kmita Andrzej</i>	
CONDITION ASSESSMENT OF SELECTED REINFORCED CONCRETE STRUCTURAL ELEMENTS OF THE BUS STATION IN KIELCE.....	514
<i>Tworzewski Pawel, Raczekiewicz Wioletta, Grzmil Wioletta, Czapik Przemyslaw</i>	
DEGRADATION OF ARCHITECTURAL PRECAST CONCRETE ELEMENTS ON THE FACADE OF ST. MICHAEL THE ARCHANGEL CHURCH IN WARSAW	525
<i>Adamczewski Grzegorz, Woyciechowski Piotr</i>	
ACOUSTIC EMISSION METHOD AS A TOOL FOR THE ASSESSMENT OF INFLUENCE OF THE TEMPERATURE VARIATION ON DESTRUCTIVE PROCESSES CREATED IN EARLY AGE CONCRETE.....	537
<i>Bacharz Magdalena, Trampczynski Wieslaw, Goszczynska Barbara</i>	
EVALUATION OF THE CONDITION OF THE EXTERNAL LAYER OF WALLS IN THE NATIONAL TECHNOLOGICAL SYSTEM "S-SZ" (SZCZECIN SYSTEM) OF LARGE-PANEL PREFABRICATED CONSTRUCTION.....	549
<i>Girus Krzysztof</i>	
THE ON-SITE EXAMPLE OF INFLUENCE OF SELECTED FACTORS ON THE QUALITY OF MONOLITHIC REINFORCED CONCRETE ELEMENTS.....	562
<i>Owczarska Kamila, Szmigiera Elzbieta, Woyciechowski Piotr</i>	
MITIGATION OF EARLY-AGE CRACKING IN CONCRETE STRUCTURES	572
<i>Schindler Anton, Byard Benjamin, Tankasala Aravind</i>	
ULTRASONIC EVALUATION REGARDING THE EFFECTS OF BIOLOGICAL CORROSION OF HISTORICAL ROOF TRUSSES.....	585
<i>Skowronski Wojciech, Stawiski Bohdan</i>	
CHEMICAL CORROSION OF CONCRETE TANK IN SEWAGE TREATMENT PLANT AS THE CAUSE OF FAILURE	595
<i>Woyciechowski Piotr, Adamczewski Grzegorz, Lukowski Pawel</i>	
CASE STUDY OF A DERECHO WIND STORM ON AUGUST 11-12, 2017 IN POLAND: PART ONE.....	607
<i>Chmielewski Tadeusz, Szer Jacek, Bobra Piotr</i>	
ANALYSIS OF CAUSES OF STRUCTURAL FAILURES OF BUILDINGS USING TQC TOOLS.....	617
<i>Czajkowska Agnieszka</i>	
MANAGING ACCIDENTS AND FAILURES OF HYDRAULIC STRUCTURES.....	625
<i>Daniel Ryszard A., Paulus Timothy M.</i>	
ANALYSIS OF STABILISATION METHOD OF GABLE WALLS OF A BARRACK LOCATED AT THE SECTION BI OF THE FORMER KL AUSCHWITZ II-BIRKENAU	638
<i>Gromysz Krzysztof, Szoblik Lukasz, Cyrulik Ewa, Tanistra-Rózanowska Agnieszka, Drabczyk Zofia, Jancia Szymon</i>	
MODELLING FAILURE PRESSURE OF PIPELINE COMPOSITE REPAIR DESIGN USING FINITE ELEMENT ANALYSIS INCORPORATING PUTTY'S CONTRIBUTION.....	648
<i>Jiang Xiaoxia, Sim Yu Ling, Doh Shu Ing, Chin Siew Choo, Lim Kar Sing</i>	

APPLICATION OF THE TAKAGA-SUGENO NEURO-FUZZY MODEL FOR DETERMINING OF ENGINEERING STRUCTURES	657
<i>Mrówczyńska Maria</i>	
THE TLS TECHNIQUE AS A WAY OF IDENTIFICATION AND MEASUREMENT OF DAMAGED ELEMENTS OF A HISTORIC SACRAL BUILDING	667
<i>Pawłowicz Joanna A.</i>	
ANALYSIS OF EXPLOITATION DAMAGES OF THE FRAME SCAFFOLDING	678
<i>Robak Aleksander, Pienko Michał, Blazik-Borowa Ewa, Bec Jarosław, Szer Iwona</i>	
HAZARDS INDUCED BY THERMAL CONDITIONS DURING WORK ON SCAFFOLDING	692
<i>Szer Iwona, Szer Jacek</i>	
LOCALIZATION AND IDENTIFICATION OF GAS INFRASTRUCTURE DEFECTS BY ACOUSTIC EMISSION	702
<i>Swit Grzegorz, Krampikowska Aleksandra</i>	
FAILURE OF THE OVERHEAD CRANE RUNWAY	715
<i>Kossakowski Paweł, Wcislik Wiktor, Bakalarz Michał</i>	
ACOUSTIC EMISSION FOR DIAGNOSING CABLE WAY STEEL SUPPORT TOWERS	723
<i>Krampikowska Aleksandra, Swit Grzegorz</i>	
PROBLEMS ENCOUNTERED WHEN ASSESSING THE TECHNICAL CONDITION OF SOME TYPES OF INDUSTRIAL STRUCTURES ON THE EXAMPLE OF COAL BUNKERS FOR A POWER BOILER	737
<i>Kubica Jan, Kaluza Marta</i>	
ANATOMY OF FAILURES: STABILITY REQUIREMENTS IN ALL STAGES OF OPERATIONS	747
<i>Moncarz Piotr, Bishop Cliff</i>	
ANALYSIS OF LOAD BEARING STRUCTURE OF SELECTED HALL BUILDINGS	758
<i>Onopiuk Sławomir, Stolarski Adam</i>	
CORROSION AS A CAUSE OF THE FAILURE OF THE PIPELINE STEEL SUPPORTING STRUCTURE	767
<i>Paczkowski Wiesław, Skibicki Szymon</i>	
FAILURE OF A STEEL BOILER CHIMNEY CAUSED BY CORROSION OF THE STRUCTURAL SHELL PLATE	779
<i>Pisarek Zdzisław</i>	
CAUSES OF HOT AND COLD WATER SYSTEM FAILURE	788
<i>Szaflik Władysław</i>	
50 YEARS HAVE PASSED, CURRENT STATE, STUDIES AND SAFETY ASSESSMENT OF HANGING ROOF ABOVE THE MAIN SPORT AND ENTERTAINMENT HALL IN KATOWICE	798
<i>Szydłowski Rafał, Labuzek Barbara</i>	
STRENGTHENING OF A STEEL GIRDER WITH WEB OPENINGS	807
<i>Wojnar Andrzej, Bernatowska Edyta</i>	
Author Index	