

Rehabilitation and Reconstruction of Buildings

Selected peer-reviewed extended articles
based on abstracts presented at the
International Conference on Rehabilitation
and Reconstruction of Buildings 2021
(CRRB 2021)

Aggregated Book

Edited by

Dr. Michaela Kostelecká

 *Scientific.Net*

Copyright © 2022 Trans Tech Publications Ltd, Switzerland

All rights reserved. No part of the contents of this publication may be reproduced or transmitted in any form or by any means without the written permission of the publisher.

Trans Tech Publications Ltd
Seestrasse 24c
CH-8806 Baech
Switzerland
<https://www.scientific.net>

Volume 32 of
Scientific Books Collection
ISBN 978-3-0357-2754-8

Full text available online at <https://www.scientific.net>

Distributed worldwide by
Trans Tech Publications Ltd
Seestrasse 24c
CH-8806 Baech
Switzerland
Phone: +41 (44) 922 10 22
e-mail: sales@scientific.net

Printed with permission by
Curran Associates Inc. (2023)

CURRAN ASSOCIATES INC.
proceedings
.com

Additional copies of this
publication are available from:

Web: www.proceedings.com/68420.html

Table of Contents

Preface	v
Committees	vi
Chapter 1: Reliability Assessment and Restoration of Concrete Structures and Elements	
Color Stability of Colored Concrete over Time Depending on the Type of Pigment M. Utěšená and R. Pernicová.....	3
Corrosion of Steel Prestressing Reinforcement - The Influence of the Used Construction Technology of Concrete Suspension Footbridges V. Vacek and P. Pokorný	9
Corrosion Properties and Bond Strength of Coated (PE/PAK; Pe/PPE; PAD) Reinforcement (B500B) with Normal Strength Concrete P. Pokorný, N. Prodanovic, K. Hurtig and M. Holeček.....	15
Degradation of Colored Concrete Elements due to Frost R. Pernicová, K. Hurtig and M. Utěšená	21
Resistance of Electrically Conductive Concrete to Sulphate Attack I.S. Polyanskikh, A.N. Gumenyuk, A.F. Gordina, I.A. Pudov and G.I. Yakovlev.....	27
Corrosion of Zinc Dust in Cement Paste - Evaluation of Hydrogen Gas Evolution Time Period P. Pokorný, N. Prodanovic, L. Topolář, L. Pazdera and I. Kusák	35
Chapter 2: Reliability Assessment and Restoration of Architectural Structures	
Chemical Analysis of the Building Material Coating from Historical Bridge in Prague K. Sladká and R. Pernicová	43
Rehabilitation of Historic Farmstead near Klecany J. Marková, P. Pokorný and P. Marek	49
Investigation of the Effectiveness of the Rehabilitation of Historical Constructions Using Wireless Dehumidification Technologies P. Šťastný	55
Long-Term Monitoring Side Chapel Church from the Point of View of Formation and Course of Condensation on its Inner Surface L. Kudrnáčová, L. Balík and K. Hurtig	63
Chapter 3: Persistence to External Factors, Protection, Treatment and Insulation	
Assessment of Chemical Resistance of Polymer Repair Mortars R. Hermann, J. Majerová, R. Drochytka and P. Figala.....	71

Effect of Carbon-Containing Additives on the Properties of Fluoroanhydrite Compositions Used for Flooring	
D. Kalabina, G.I. Yakovlev, Z. Saidova, G. Pervushin and A.F. Gordina	77
Experimental Testing Results of a Timber Structure's Fire Resistance in a Combustion Chamber	
T. Žajdlík and K. Šuhajda	83
Influence of Moisture and Density of Wood on the Depth of Holes Made by a Kučera's Drilling Machine	
P. Černý, E. Frimlová and V. Heřmánková	89
Influence of Physical and Chemical Stress on the Properties of CIPP Pipes Based on Vinyl Ester	
J. Hodul, L. Mészárosová and J. Majerová	95
Study of the Preparation of Micronized Zinc Phosphate Dihydrate with Potential for Application in the Phosphating Process	
A. Zabloudil, N. Prodanovic, P. Pokorný, J. Kolisko and K. Cech Barabaszova	103
The Use of Thin-Layer Insulation Material in Technical Installations in Building Reconstructions	
P. Vrbová and L. Prokopová	111
Chapter 4: Structural Health Monitoring and Reliability Level Assessment	
Comparison of Different Sensors Used in the Assessment of Concrete Elements by Impact-Echo Method	
J. Puchýř, R. Dvořák, A. Hubáček and Z. Chobola	121
Detection of Internal Defects and Failures of Concrete Structures Using Non-Destructive Methods	
J. Šnědar, V. Bartoň and P. Cikrle	129
Study of Microstructure of Electrically Conductive Silicate Composites with Graphite-Based Fillers	
Š. Baránek, L. Mészárosová, R. Drochytka and G.I. Yakovlev	135
The Expansion of Defects of Solid Fired Bricks due to their Freezing	
V. Bartoň, J. Šnědar and P. Cikrle	145
Effect of Target Reliability Level on Partial Factors for Existing Steel Railway Bridges	
V. Nadolski, M. Holicky and M. Sýkora	153
Introductory Chapter to Microbially Induced Deterioration of Concrete - Focus on Groups of Typical Microorganisms	
P. Pokorný	163
Keyword Index	169
Author Index	171