

68th Annual Safety in Ammonia Plants and Related Facilities Symposium 2024

AICHE Technical Manual 2024 Volume 64

San Diego, California, USA
9 - 12 September 2024

ISBN: 979-8-3313-0264-1

Printed from e-media with permission by:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571

Some format issues inherent in the e-media version may also appear in this print version.

Copyright© (2024) by AIChE
All rights reserved.

Printed with permission by Curran Associates, Inc. (2025)

For permission requests, please contact AIChE
at the address below.

AIChE
120 Wall Street, FL 23
New York, NY 10005-4020

Phone: (800) 242-4363
Fax: (203) 775-5177

www.aiche.org

Additional copies of this publication are available from:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571 USA
Phone: 845-758-0400
Fax: 845-758-2633
Email: curran@proceedings.com
Web: www.proceedings.com

TABLE OF CONTENTS

Lessons Learned from Investigations of Ammonia Incidents.....	1
<i>V.A. Tabrizy, B. Moltu, A. Forland, S.H. Nilsen</i>	
Improvement of Mitigation Barriers in Fire Case: A Study Case from the Ammonia Converter	15
<i>Z.S. Rahman, G.H. Pratomo, D.D. Ananda, R.Q. Gobel, B.A. Nugraha</i>	
101-B Primary Reformer Riser Transitional Assembly Failure.....	25
<i>C. Ramdin, S. Okulaja</i>	
Unusual Fire Beneath a Steam Methane Reforming Furnace.....	33
<i>B. Ross, K. Wohlgeschaffen</i>	
Reliability of Outlet Systems of Primary Reformer for the Safe Operation of a Syngas Plant	39
<i>C. Thomas, P. Ravulaparthi</i>	
Hydrogen Assisted Cracking (HAC) in the Ammonia Synthesis Loop	51
<i>S. Cavalleri, G. Paci, R. Bosselaar, C. Hamelink</i>	
Titanium and Zirconium Corrosion Benefits and Reactivity Concerns in Ammonia and Nitric Acid Process Equipment	61
<i>D.J. Benac, M. Kral, D. Shaffer</i>	
Repeated Secondary Reformer Waste Heat Boiler (101-C) Tube Rupture and Following Effects.....	71
<i>P.A. Pratama, F. Kurniawan, D. Jatiningih</i>	
Recent Findings About Flow Accelerated Corrosion (FAC) in Aqua Ammonia Loops	83
<i>S. Cavalleri, G. Paci, R. van Lier, R. Babwah</i>	
Unprecedented Catalyst Overheating Due to Feed Preheat Coil Failure.....	95
<i>T.A. Pradibta, R. Sarjaka, Ariffianto</i>	
Once Through Ammonia Converter for Revamp of a Fertilizer Facility.....	105
<i>R. Solunke, J. Brightling, D. Meurer</i>	
Challenges Experienced in the Longest Run of HTS Catalyst	113
<i>K.H. Chew, T. Archer, T.H. Ng, V. Pattabathula, N. Amin, S. Maule</i>	
Re-Activation of Poisoned Ammonia Synthesis Catalyst at OCI Nitrogen.....	121
<i>C.R. Hansen, A. Ghani, P. de Konink, L. Murrer, G. Decramer</i>	
Demolition of Secondary Reformer Air Insert and Transfer Line Repair Without Replacing Incoloy 800H/HT Liner	129
<i>M. Kumar, M. Markus</i>	
Failure Occurred at the Primary Reformer Tubes of Ammonia 1B Plant at PT Pupuk Kujang.....	137
<i>Z. Arsadduddin, Maryono, A.P. Putra, R.A. Keswantono</i>	
Challenging Repair Solutions for Recurring Leaks in a High-Pressure Carbamate Condenser	147
<i>G. Paci, H. Hauschild, M. Schmahl</i>	
Safety Aspects of Green Ammonia Production	159
<i>E. Sorensen, G. Rexwinkel, V. Pattabathula</i>	

Learnings During Engineering for Autothermal Reformer-Based Ammonia Plant	169
<i>B. Mielke</i>	
Reliability and Safety of Oxygen Blown ATRs to Enable Low Carbon Ammonia	179
<i>M.J. Cousins</i>	
Primary Reformer Riser Transition Assembly Damage, Repair, and Future Risk Mitigation Plan	191
<i>M. Kumar, M. Markus, R. Kabs, Abhishek</i>	
E-208 Nitric Acid Cooler Condenser Failures	199
<i>S. Okulaja, K. Adejare</i>	
Synthesis Gas Compressor Oil-Seal Failure with Fire	205
<i>C. Dias, M. van Graefscupe, R. Grunow</i>	
Maritime Spills of Cold/Refrigerated Ammonia: Thermodynamic Model for Predicting Behavior	211
<i>C. Rzepa, S. Dharmavaram, B.H. Ko, V. Parekh</i>	
Evaluation of Safety Instrumented System in Ammonia Plant Using HAZOP, LOPA, and RBD Analysis	221
<i>H. Qosim, M. Azmi, S. Abdurrakhman, R. Azzahra, M.H. Amsori</i>	
Prioritizing Safety Culture for Ammonia as a Fuel in Energy Transition	231
<i>M.I. Gandhi, D. Shaffer, D.J. Benac</i>	
Steam Methane Reformer Outlet System – Mechanical Integrity	243
<i>C. Texter, S. Dharmavaram, J. Cassell</i>	
High Temperature Equipment Service Damage Identification and Inspection	253
<i>M. Bell, A. Benz</i>	
Analyzing Ammonia Dispersion Under Varying Atmospheric Conditions Using DRIFT	263
<i>R. Hetherington, A. McGillivray, S. Gant, G. Tickle</i>	
IMTP Packing Carry Over: Massive Damage in 2nd Packed Bed of Ammonia Plant CO2 Stripper	271
<i>M. Fahmi, H. Tondeang</i>	
Operating Experience and Improvement in Operational Practices in 32 Years-Old SS-316 Lined Urea Reactors	277
<i>M.U. Liaquat, A. Ahmad</i>	
Enhancing Reliability and Performance in Ammonia Plant Operations: Managing WHB Leaks and Catalyst Preservation	285
<i>R. Rahman, A. Swandaru, M.M. Maulana, G.P. Gemilar, A. Ferdiawan, Z.A. Fikri, A. Lusdiono</i>	
Replacement of Superheater Module in Primary Reformer Convection Section	293
<i>S. Mathur, A.S. Chauhan</i>	
Ammonia as a Fuel: Evaluating Safety Aspects, Addressing Key Gaps, and Indicating the Way Forward	305
<i>V.A. Tabrizy, S.H. Nilsen, T. Ryberg, J. Belgaroui, B.O. Neeraas</i>	
Improvement of Mitigation Barriers in Fire Case: A Study Case from the Ammonia Converter	315
<i>Z.S. Rahman, G.H. Pratomo, D.D. Ananda, R.Q. Gobel, B.A. Nugraha</i>	

Author Index